


CITY OF BALTIMORE WET WEATHER CONSENT DECREE SMOKE AND DYED WATER TESTING FORM		Page 1 of 4
Sewershed: Low Level Subsewershed: 44	Company: REI/DRAYCO	Date: 09/02/2008
Test Type: Smoke	Ground Condition: Dry: X Damp: _ Wet: _	Supervisor: E.R. Crew: 04
Manhole ID: S19O__008MH	Test ID: 1029-583	Notifications Made: __X__ Residents, Fire, 311
Field Sketch: (Show all manholes with numbers, blower placement location, sandbag or isolation locations, street names, building addresses and locations, defect locations and photograph numbers)		



[illegible]

CITY OF BALTIMORE
SMOKE TESTING OBSERVATION SUMMARY
LOW LEVEL SEWERSHED
BALTIMORE CITY PROJECT 1029
REI/DRAYCO

Unique Test ID: 583	Date: 09/02/2008	Basin: LL - 44	Manhole ID: S190__008MH
Defect No: OB01	Supervisor: E.R.	Crew: 04	Dye Test Recommended: N
Location: 502 S. BENTALOU ST.			

Source Type: 18 Other

Sector: 02 Private

Location: 14 Other

Severity: 03 Moderate

Drainage Area: 0

Comments: THE SMOKING VENT HERE INDICATES THAT A SANITARY LINE EXISTS FROM S190__011MH TO THE END OF THE BLOCK, THAT IS NOT PICTURED ON MAP. OTHERWISE, THERE IS NO DEFECT.

SMOKE TEST PHOTOGRAPHS



Photograph No: OB01-01
Filename: 1029-583_OB01-01.jpg

CITY OF BALTIMORE
SMOKE TESTING OBSERVATION SUMMARY
LOW LEVEL SEWERSHED
BALTIMORE CITY PROJECT 1029
REI/DRAYCO

Unique Test ID: 583	Date: 09/02/2008	Basin: LL - 44	Manhole ID: S19O__008MH
Defect No: OB01	Supervisor: E.R.	Crew: 04	Dye Test Recommended: N
Location: 528 S. BENTALOU ST.			
Source Type: 18 Other	Sector: 02 Private		
Location: 14 Other	Severity: 03 Moderate	Drainage Area: 0	
Comments: SMOKE IS COMING FROM UNKNOWN DEFECT HIDDEN BY MATTRESSES AT ADDRESS.			

SMOKE TEST PHOTOGRAPHS



Photograph No: OB01-01
Filename: 1029-583_OB01-01.jpg